


Fusible Stay tape

DRCOS

SITE [http://dr-cos.info\(en\)](http://dr-cos.info(en)) [http://dr-cos.com\(jp\)](http://dr-cos.com(jp))
MAIL info@dr-cos.com
Twitter https://twitter.com/@drcos_com
facebook <https://www.facebook.com/drcoscom>

LADIES



Circular Skirt
body
three sheets

Bonding line AA

Bonding line Aa

Bonding line AA

Grain Line



11.8in length cut line

13.8in length cut line

15.7in length cut line

Bonding line AB

Bonding line Ba

Bonding line AB


17.7in length cut line

19.7in length cut line



21.7in length cut line

Bonding line Ca

Bonding line AC




Seam allowance 1/2in.




Skirt 5
y
neets


Bonding line Ab


Bonding line BA


















Circular Shaft
Fusible interface
Belt
one sheet



Bonding line Bc

Bonding line DA

Bonding line DB

Bonding line Bd

LADIES' M

ar Skirt 5
Belt
sheets
interlining
sheets

Seam allowance 1/2in.

Bonding line DB


Bonding line DC

Bonding line Cc

Bonding line Cd

Bonding line Dc

Bonding line DC



DRCOS
SITE <http://dl-cos.info/en> <http://dl-cos.com/jp>
MAIL: info@dl-cos.com
Twitter https://twitter.com/drcos_com
facebook <https://www.facebook.com/drcoscom>

Bonding line DD

Bonding line Dd