

Fusible Stay


DRCOS

SITE [http://dr-cos.info\(en\)](http://dr-cos.info(en)) [http://dr-cos.com\(jp\)](http://dr-cos.com(jp))
MAIL info@dr-cos.com
Twitter https://twitter.com/@drcos_com
facebook <https://www.facebook.com/drcoscom>

Bonding line Aa

MEN

Circ



thre

Bonding line AA



Bonding line AA



Grain Line




11.8in length cut line

13.8in length cut line

Bonding line AB

Bonding line Ba



Bonding line AB

15.7in length cut line

17.7in length cut line

19.7in length cut line


21.7in length cut line

Bonding line AC

Bonding line Ca

Seam allowance 1/2in

Stable Stay tape




Bonding line Aa




Bonding line Ab


Circular Skirt 5
body
three sheets


Bonding line BA







ce 1/2in.










Bonding line Ac

Bonding line Ad

Bonding line DA



Bonding line DA

Bonding line Bc

Placket

Bonding line Bd

Bonding line DB

Grain Line

Bonding line Cc

Bonding line DB

Seamallo

Bonding line DC

**Circular Skirt 5
Belt
one sheets
Fusible interlining
one sheets**

Bonding line Cd

Bonding line Dc

Bonding line DC

seam allowance 1/2in.


Bonding line DD

Bonding line Dd

MEN'S
IT
SIZES

Bonding line Ec

Bonding line DD



DRCOS
SITE <http://dr-cos.info/en/> <http://dr-cos.com/jp/>
MAIL info@dr-cos.com
TWITTER https://twitter.com/@drcos_com
FACEBOOK <https://www.facebook.com/mvdrcooscom>

Bonding line Ed