

DRCOS

SITE [http://dr-cos.info\(en\)](http://dr-cos.info(en)) [http://dr-cos.com\(jp\)](http://dr-cos.com(jp))

MAIL info@dr-cos.com

Twitter [@drcos_com](https://twitter.com/@drcos_com)

facebook <https://www.facebook.com/drcoscom>

Bonding line AA

Bonding line AA




Bonding line AB

Bonding line Ba


LADI

Bonding line AB




Bonding line Ca

Bonding line AC



Bonding line BA

Baste




Pleat Skirt(fake)
body
two sheets

Bonding line Ba

Bonding line Bb

Grain

Bonding line BB



Bonding line Ca


Grain Line

Bonding line BB

Bonding line Cb

Seam allowance 1in.

Bonding line BC



Bonding line Ab

Fusible Stay tape

Placket


Bonding line CA

Bonding line Ac

Bonding line Bc

Box Pleat Skirt 2
Belt
one sheets
Fusible interlining
one sheets

Grain Line



Bonding line CA

Seam allowance

Bonding line CB

Seam allowance 1/2in.


Fastener end



Bonding line Bb

Bonding line CB
allowance 1/2in.

Bonding line Cb



Bonding line CC

Bonding line Cc

Bonding line Db

Bonding line CC



Bonding line Dc

Bonding line CD