

Placket

Grain Line

Bonding line AA

Bonding line Aa

Bonding line AA

Bonding line Ba

Long Flared Skirt
Belt
one sheets
Fusible interlining
one sheets

Bonding line AB

Seam allowance 1/2in

nce 1/2in.

Bonding line AB

MEN'S
IG
size

Bonding line AC

Bonding line Ca

Bonding line AC

Bonding line Da



DRCOS
SITE <http://drcos.info/en> | <http://drcos.com/tp>
MAIL info@drcos.com
Twitter <https://twitter.com/drcos> | www.facebook.com/drcoscom


Bonding line AD


Bonding line BA

Bonding line Ba

Bonding line Bb

Bonding line BB






Bonding line BC

Bonding line Da

Bonding line Db

Bonding line BD



Bonding line Ab


Bonding line Ac

Bonding line CA

Fusible Stay tape

Fastener end

Baste



Bonding line CA


Bonding line Bb

Bonding line Bc

MEN'S **L** size


Long Flared Skirt
Body

Bonding line CB



two sheets

Bonding line CB



Body
two sheets

Bonding line Cb

Bonding line Cc

Bonding line CC



Grain

Bonding line CC

Grain Line




Bonding line Db

Bonding line Dc

Seam allowance 1/2in.

Bonding line CD



Bonding line DA

Bonding line Bc

Bonding line Bd



size

rt

Bonding line DB



Bonding line DB



Bonding line Cc

Bonding line Cd

Bonding line DC

Bonding line DC

Bonding line Dc

Bonding line Dd

DRCOS

SITE <http://dr-cos.info/en> <http://dr-cos.com/jp>

MAIL info@dr-cos.com

Twitter https://twitter.com/drcos_com

facebook <https://www.facebook.com/drcoscom>

Bonding line DD