

Bonding line AA


Seam allowance 1/2in.

Baste

Fastener end

Bonding line Ba

Bonding line AB



Bonding line AB




Grain Line

Bonding line Ca

ack

Switching pleated done piece  
Back Body  
two sheets

MEN'S



size

Bonding line




Fusible Stay tape

Facing line

**DRCOS**  
SITE <https://drcos.info/en> [https://drcos.com\(dp\)](https://drcos.com(dp))  
MAIL [info@drcos.com](mailto:info@drcos.com)  
Twitter [https://twitter.com/drcos\\_com](https://twitter.com/drcos_com)  
Pinterest <https://www.pinterest.jp/drcosinfo>

Bonding line Da

Bonding line AD




Bonding line AD



Bonding line Ea

Bonding line AE



Bonding line BA

Seam allowance 1/2in.

Bonding line Ba

Bonding line Bb



Bonding line BB

Bonding line BB

ingpleatedonepiece  
Sleeve  
two sheets





Bonding line Ca  
Back

Bonding line Cb

DRCS  
[https://dr-cos.info\(en\)](https://dr-cos.info(en)) [https://dr-cos.com\(jp\)](https://dr-cos.com(jp))  
[info@dr-cos.com](mailto:info@dr-cos.com)  
[https://twitter.com/dr-cos\\_com](https://twitter.com/dr-cos_com)  
<https://www.pinterest.jp/dr-cosinfo>

Bonding line BC








Bonding line CA

Se

Bonding line Bb

Bonding line Bc

Bonding line CB



**DRC**  
SITE <https://dr-cos.intel.com>  
MAIL [info@dr-cos.com](mailto:info@dr-cos.com)  
Twitter <https://twitter.com/dr-cos>  
Pinterest <https://www.pinterest.com/dr-cos>

**MEM**

Switching  
S  
two


Bonding line Cb


Bonding line CB


Bonding line CC

Bonding line Cc


Front








Bonding line Ac



Bonding line Ad

Bonding line DA



# MEN

Bonding line DB

Bonding line Cc


Bonding line Cd

Pleat matching position


Pleat Line

Pleat Line

Bonding line DC



Bonding line DC



Switching pleated one piece  
 Pleat  
 two sheets

Bonding line Dc

Bonding line Dd

Bonding line DD



Bonding line DD

Bonding line Ec

Bonding line Ed

Bonding line DE




Facing line

Bonding line Ad

Bonding line Ae

Bonding line EA






Bonding line EA

Bonding line Bd

Bonding line Be

Bonding line EB



Bonding line EB

position

Bonding line Cd

Bonding line Ce

Pleat Line

Bonding line EC

Switching pleats  
Back Body  
two sheets

apleatedonepiece  
Body(side)  
sheets

Bonding line EC

piece  
sheets

Bonding line Dd

Seam allowance 1/2in.

# MEN'S



Bonding line De

**DRCOS**  
SITE <https://drcos.info/en> <https://drcos.com/fp>  
MAIL [info@drcos.com](mailto:info@drcos.com)  
TWITTER <https://twitter.com/drcos>  
Pinterest <https://www.pinterest.jp/drcosinfo>

Bonding line ED

Bonding line Ed

Bonding line ED



# MEN'S

Switchingpleatedonepiece  
Front Body  
one sheets



**DRCOS**  
SITE <https://dr-cos.info/en> <https://dr-cos.com/jp>  
MAIL [info@dr-cos.com](mailto:info@dr-cos.com)  
Twitter [https://twitter.com/dr-cos\\_com](https://twitter.com/dr-cos_com)  
Pinterest <https://www.pinterest.jp/drcosinfo>

Bonding line Ee

Bonding line EE


Bonding line FB

Bonding line Ce

Bonding line Cf

Seam allowance 1/2in.

Grain Line




Switching

Bonding line F

MEM


Bonding line F

MEN'S



Switchingpleatedonepiece  
Back Facing


Fusible interlining  
two sheets



Seam allowance 1/2in.

Bonding line De

Switch



Grain Line



Symmetry


Bonding line D

onepiece  
(epis  
sets

Bonding line FD

S





# MEN'S

Switching pleated one  
Front Body (side  
two sheets

Bonding line FD




Grain Line

Bonding line Ee

Bonding line Ef




Grain Line



Symmetry

Bonding line FE



Switching pleated one piece  
 Front Facing  
 Fusible interlining  
 one sheets

Bonding line D



Seam allowance 1/2in.

Bonding line GD

Seam allowar

Bonding line Ef

Seam allowance 1/2in.

Bonding line GE

